

## **DIGITAL THERMO HYGROMETER - HT-1026HI**

### **RANGE:**

**Temperature:** Indoor: -10°C to 50°C (14°F to 122°F)  
Outdoor: -50°C to 70°C (-58°F to 158°F) (if applicable)

**Relative Humidity:** 20% to 95% (if applicable)

### **MAX/MIN MEMORY:**

Press the MAX button once to show the maximum records of temperature and humidity.  
Press the Max button again to return to current readings.

Press the MIN button once to show the minimum records of temperature and humidity.  
Press the MIN button again to return to current readings.

Press the RESET button to reset the MAX or MIN record when the Max or Min record is displayed.